

AM



PYF

AL



PTF

Socket: PYF

Resistive load: 3A / 5A / 10A

Motor load: 1/3Hp,120VAC / 1/2Hp,240VAC

No. of contacts: 2C / 3C / 4C

Coil voltage: 6VDC-110VDC / 6VAC-240VAC

Socket: PTF

Resistive load: 10A / 12A / 15A / 20A

Motor load: 1/3Hp,120VAC / 1/2Hp,240VAC / 3/4Hp,240VAC


No. of contacts: 1C / 2C / 3C / 4C

Coil voltage: 6VDC-110VDC / 6VAC-240VAC

ART1



PF / TP



AP



Socket: PF/TP

Resistive load: 1A

No. of contacts: 4NO/2NO&2NC/3NO&1NC/4NC

Coil voltage: 12VDC/24VDC/48VDC/110VDC

Resistive load: 5A

No. of contacts: 2C

Coil voltage: 5VDC / 6VDC / 12VDC / 24VDC

36VDC / 48VDC / 110VDC

Application: industrial automation control, rail transport, power control.....